	Approved For Release 2002/06/07CCIA-RDP701	47A002900050018-7		
	77			
		11 March 1966	STATINTL	
		CW 66-2051 REF: AO-501-AA		
STATI	VIL			
Г				
,,,,,,	\$ 9 5 had a \$ \$9 51 a			
	Additional Funding			
	Reference: (a) OTC Letter CW 66-2012, date	ed 8 February 1966		
	• •	-	STATINTL	
STATI	Gentlemen:		SIAIINIL	
SIAIII	In accordance with Reference (a)			
	hereby requests that the su	biect Task Order be ame	 nded	
	to provide additional funding and that the delivery date be extended to 1 April 1968.			
	We feel that the increase in funding and extension of delivery are justified for the			
	following reasons, and are in compliance with Section	n E, Article 12 of the sui	oject	
	contract, entitled "Changes".		STATINTL	
	The original concept called for cutting away a portion	of the negative	carrier	
, indigen	casting and adding a precision slide to provide plus of	or minus $1-1/2$ inches no	gative	
	adjustment. In addition, the light shield assembly w	as to be modified to allo	w the	
OT 4 TI	negative slide to shift.			
STATI	NIL Inspection of the VG-1 Enlarger at the customer's site	s, subsequent to the awa	rding	
	of contract, showed that the original concept of using			
	to mount the slide bearings and shafts was not feasib	le as the Enlarger incorp	orates	
	an adjustable mask assembly in this space. This ass			
	drawings or manuals in our possession and was		25X1	
	Enlarger shown to our representative prior to the properties mask assembly it was necessary to keep the new slid			
	bare minimum so that a clearance exists between the			
				
	Declass Review by NIMA/DOD			
			STATINTL	

Approved For Release 2002/06/17 : CIA-RDP78B04747A002900050018-7

STATINTL

STATI	<u>YTL</u>				
	Approved For Release 2002/06/17 : CIA-RDP78B0	04747A002900050018-7			
	Page 2	11 March 1966			
STATI	The bearings and shafts had to be placed out-board of t casting. The net result was a thin casting (slide) with bearing supports. This would not result in the stability product and many design hours were spent in beefing up causing interferences.	a long span between	STATINTL on out		
	Considerable difficulty was encountered in locating ventors casting and the slide assembly. Both castings machines and two months investigation showed no vendo could give reasonable delivery and cost. It was therefore fixtures would be made to allow in-house machining of design of the slide casting was modified to the extent in bearing location tolerances to be met by machining and desired approach of machining only.	required larger than norm ors were available who ore decided that special the two castings. The ecessary to permit final	al		
	In summary it can be said that much additional design time was spent due to the incomplete definition of the parameters of the design area, and additional time and costs were encountered due to the lack of response by outside machining services. The following is a cost breakdown of the funding required to complete the project, not including fee which will be applied at completion.				
			STATINTL		

STATINTL Approved For Release 2002/06/1	7 : CIA-RDP78B04747A002900050018-7
Page 3	11 March 1966
It should be noted, that as a result of a me representatives, a proposal will be forther at that time.	
For further information, please contact Administration.	Manager, Contract STATINTL
	Very truly yours,
•	

DJS:bs